



DELLAVALLE®
Laboratory, Inc.
Chemists and Consultants

Report of Water Analysis

1910 W. McKinley, Suite 110, Fresno, CA 93728
FAX (559) 268-8174 - (800) 228-9896 - (559) 233-6129

Sedona Geologic
2904 N Thorne Avenue
Fresno CA 93704
17345
50

Material Submitted: Water

Lab No. 180897
Sampler Client
Submitted Date 11/6/2012
Submitted by
Reported Date 11/14/2012
Location/Project Reeve Rd. Heifer Ranch
Copy To
Fax
e-mail cskelton@sedonageologic.com

	Date	Time	NO ₂ -N	NO ₃ -N	Total NH ₄ -N	Total TKN
	Sampled	Sampled	mg/L	mg/L	mg/L	mg/L
MCL-->			3.0	10.2		
MDL-->			0.004	0.01	0.2	0.7
RL-->			0.1	0.1	0.5	1
SM-->					4500NH ₃ G	4500NH ₃ G
EPA-->			300.0	300.0		
Analysis Date:	11/7/2012	11/7/2012	11/7/2012	11/7/2012	11/8/2012	11/9/2012
Analysis Time:	18:29	18:29	18:29	18:29	14:18	

001	GW - B - 3	11/6/2012	12:30	<0.4	1.5	0.5	<1.0
002	GW - B - 2	11/6/2012	12:50	<0.4	0.8	137	175

*See external laboratory documentation

pH analyzed outside of 15 min hold time.

MCL = Maximum Contaminant Level according to the California Domestic Water Quality and Monitoring Regulations (Title 22)

MDL = Method Detection Limit; **RL** = Reporting Limit

SM = Standard Methods for the Examination of Water and Wastewater, 19th ed., 1995

Dissolved metals (**bolded**) were filtered.

QA/QC available upon request.

Approved By: _____
ELAP Certification #1595